

Frame Connectors



Frame connectors connect the side frames of two conveyors in one line. Their special form guarantees alignment of the side frames. Four frame connectors are normally required to connect two conveyor modules together.

Description	Dimensions " (mm)	Reference number
Frame Connectors	3.15 (80) x 0.75 (20)	31753