


# SRZ-40 PRESSURE DROP CURVES





<b>AW-COMPANY</b> FRANKLIN, VT 05450	
TITLE: SRZ-40 PRESSURE DROP	
DRAWING NUMBER: SRZ40PD	
DRAWN BY: GUS SKIAKER	
DATE: 01-28-94	CHECKED BY: A.B.
PAGE 1 OF 1	SCALE: NONE

THIS PRINT, INCLUDING THE INFORMATION CONTAINED HEREIN, IS THE PROPERTY OF AW-COMPANY; IT IS CONSIDERED PROPRIETARY IN NATURE AND MAY NOT BE USED OR DISCLOSED OUTSIDE OF AW-COMPANY EXCEPT UNDER WRITTEN AGREEMENT. ANY MODIFICATIONS MADE TO OR COMMENTS WRITTEN ON THIS DRAWING BY UNAUTHORIZED PERSONNEL WILL VOID THIS DRAWING.

# SRZ-100

## PRESSURE DROP CURVES



		<b>AW-COMPANY</b> FRANKSVILLE, VT 05445
TITLE: SRZ-100 PRESSURE DROP		
DRAWING NUMBER: SRZ100PD		
DRAWN BY: GUS SKIAKER		
DATE: 01-28-94		CHECKED BY: A.B.
PAGE 1 OF 1		SCALE: NONE

THIS PRINT, INCLUDING THE INFORMATION CONTAINED HEREIN, IS THE PROPERTY OF AW-COMPANY. IT IS CONSIDERED PROPRIETARY IN NATURE AND MAY NOT BE USED OR REPRODUCED OUTSIDE OF AW-COMPANY EXCEPT UNDER WRITTEN AGREEMENT. ANY MODIFICATIONS MADE TO OR COMMENTS NOTED ON THIS DRAWING BY AUTHORIZED PERSONNEL WILL VOID THIS DRAWING.